

DRY ROOM 상대습도 & PPM 조건표

(단위 : %)
: PPM

건구온도(°C) 노점온도(°C)	20	20.5	21	21.5	22
-28	2.00	1.99	1.88	1.82	1.77
	288.22	←	←	←	←
-30	1.63	1.58	1.53	1.48	1.44
	234.47	←	←	←	←
-32	1.32	1.28	1.24	1.20	1.17
	190.09	←	←	←	←
-34	1.07	1.03	1.00	0.97	0.94
	153.57	←	←	←	←
-36	0.86	0.83	0.81	0.78	0.76
	123.62	←	←	←	←
-38	0.69	0.67	0.65	0.63	0.61
	99.15	←	←	←	←
-40	0.55	0.53	0.52	0.50	0.49
	79.22	←	←	←	←
-42	0.44	0.42	0.41	0.40	0.39
	63.05	←	←	←	←
-44	0.35	0.34	0.33	0.32	0.31
	49.98	←	←	←	←
-46	0.27	0.27	0.26	0.25	0.24
	39.46	←	←	←	←
-48	0.22	0.21	0.20	0.20	0.19
	30.20	←	←	←	←
-50	0.17	0.16	0.16	0.15	0.15
	24.28	←	←	←	←
-52	0.13	0.13	0.12	0.12	0.12
	18.92	←	←	←	←